

AMS02-PDS

DOC N°: PDS-RP-CGS-045

ISSUE: 1

DATE: 01/09/2008

PAGE: 1 of 2

INSPECTION REPORT

APPLICABLE DOC. REF.

PROC. REF.

AMS02-PDS PFM Manufacturing and Inspection Plan PDS-PL-CGS-001

N.A.

ITEM INSPECTED (Name, P/N, S/N) AMS02-PDS PFM – Visual inspection of some Piggy Back Boards before partially conformal coating –- Inspection Point.

REQUIREMENT SATISFIED

Manufacturing according to aerospace standards

INSPECTION (Action/Results)

DESCRIPTION

Inspection was performed at Carlo Gavazzi Space premises starting on 1 September 2008 and was carried out on the following boards before partially conformal coating applied only on one layer, detail of the inspected boards were below reported:

- 1) AUX DC/DC BOARD ASSY p/n:11-AMS02PDS-740.00 s/n:07-016 / G.
- 2) AUX DC/DC BOARD ASSY p/n:11-AMS02PDS-740.00 s/n:07-016 / B.

HARDWARE REVIEW

1) AUX DC/DC BOARD ASSY p/n:11-AMS02PDS-740.00 s/n:07-016 / G, Assy:11-AMS02PDS-740.00 rev./, Parts List:11-AMS02PDS-740.02 rev./, Electrical Scheme:11-AMS02PDS-740.03 rev./, Master PCB:SPO-PD-020010-DR-03-CGS rev./.

The following NCRs were presented during the inspection:

- NCR-PDS-CGS-C-040(electrical connection missing on pcb), NCR classified "minor" is closed.
- NCR-PDS-CGS-C-042(OVC protection improvement), NCR classified "minor" is closed.

The following PLVSs (Parts List Variation Sheet) were presented during the inspection:

- 11-AMS02PDS-740.02 rev / A2 can be considered closed.
- 11-AMS02PDS-740.02 rev / A10 can be considered closed.
- 11-AMS02PDS-740.02 rev / A13 can be considered closed.
- 11-AMS02PDS-740.02 rev / A15 can be considered closed.
- 11-AMS02PDS-740.02 rev / A16 can be considered closed.
- 11-AMS02PDS-740.02 rev / A18 can be considered closed.
- 11-AMS02PDS-740.02 rev / A21 can be considered closed.

The H/W has been visually inspected and is ok: no damage, visible clean is ok.

| | Operator | Quality Assurance | C.C. |
|-----------|----------|-------------------|-------------|
| Signature | | E. FRANCINI | C.CINQUEALY |
| Date | | In 2 01/08/08 | enje |



AMS02-PDS

DOC N°: PDS-RP-CGS-045

ISSUE: 1

DATE: 01/09/2008

PAGE: 2 of 2

INSPECTION REPORT

| APPLICABLE DOC. REF. | | |
|---------------------------------|------------|--|
| | PROC. REF. | |
| See page 1 | See page 1 | |
| ITEM INSPECTED (Name, P/N, S/N) | | |
| See page 1 | | |
| REQUIREMENT SATISFIED | | |
| See page 1 | | |
| INSPECTION (Action/Results) | | |

2) AUX DC/DC BOARD ASSY p/n:11-AMS02PDS-740.00 s/n:07-016 / B, Assy:11-AMS02PDS-740.00 rev./, Parts List:11-AMS02PDS-740.02 rev./, Electrical Scheme:11-AMS02PDS-740.03 rev./, Master PCB:SPO-PD-020010-DR-03-CGS rev./.

The following NCRs were presented during the inspection:

- NCR-PDS-CGS-C-040(electrical connection missing on pcb), NCR classified "minor" is closed.
- NCR-PDS-CGS-C-042(OVC protection improvement), NCR classified "minor" is closed.

The following PLVSs (Parts List Variation Sheet) were presented during the inspection:

- 11-AMS02PDS-740.02 rev / A2 can be considered closed.
- 11-AMS02PDS-740.02 rev / A5 can be considered closed.
- 11-AMS02PDS-740.02 rev / A13 can be considered closed.
- 11-AMS02PDS-740.02 rev / A15 can be considered closed.
- 11-AMS02PDS-740.02 rev / A16 can be considered closed.
- 11-AMS02PDS-740.02 rev / A17 can be considered closed.
- 11-AMS02PDS-740.02 rev / A21 can be considered closed.

The H/W has been visually inspected and is ok: no damage, visible clean is ok.

CONCLUSION

All solder joints are of adequate quality, the soldering process complies to ECSS-Q-70-08A and ECSS-Q-70-38A, all modifications are performed according to ECSS-Q-70-28A.

| - Wrong | Operator | Quality Assurance | · C.C. |
|-----------|----------|-------------------|--------------|
| Signature | | 5 000 | C.CINQUERAMI |
| Date | | 12 01/09/08 | enger |
| | | 100 | 4918 |